



# Minnesota's State Capitol



# Third Floor

# Minnesota's State Capitol



Room 317  
MN Capitol Art 1907 &  
and Restoration 2011-2017


Room 317A  
Two large controversial  
paintings relocated from  
Governor's Reception  
Room + commentary

Room 317 B  
MN Capitol  
Design and Construction  
1895-1907

Third Floor

# Basement Level

Basement Stonework and Public Spaces. - Before the 2011-2017 repair and restoration project these basement areas were office, storage and mechanical spaces. The large central space Room B-15 held communications wiring dating from 1900 to 2011. Virtually all of the visible stonework was either painted or hidden behind painted walls



Basement Level